

1.2.1

June 26, 1998

Mr. Carl Johnson, P.Eng.
Head, Industrial Section
Ministry of Environment, Lands & Parks
#401 - 333 Victoria Street
Nelson, B.C.
V1L 4K3



Dear Sir:

Re: Your request from the June 11th 1998 meeting at Cominco Ltd., Trail B.C. pertaining to the quantity and analysis of slag material that will remain on the Columbia river bank located north of Trail's Arena complex after demolition of the slag launders.

The enclosed historical photo shows the considerable amount of slag which developed into part of the existing Cominco south Tadanac property.

The assay results you requested from this area were six random samples of this area are:

S	CU	FE	ZN	PB	AG
%	%	%	%	%	OZ/TON
1.1	0.01	29.7	15.6	1.94	0.15
0.9	0.56	25.9	8.2	0.13	1.30
1.8	2.99	21.6	10.9	3.36	4.00
1.0	0.27	29.4	11.1	1.62	0.45
1.2	1.32	29.0	11.8	2.29	1.60
1.3	2.39	23.0	13.9	3.68	2.05

Please contact me if you require additional information.

Yours truly

A handwritten signature in dark ink, appearing to read 'G.J. Gawryletz', is written over a horizontal line.

G.J. Gawryletz
Group Leader, Environmental Monitoring

cc GFK. GMB. WID. GRW

USEPA SF



1178702